

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- ✓• TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



INSERT TOWER PERSPECTIVE VIEW

FIG. 1A




FIG. 1B

200

DELIVERY SECTION SIDE VIEW




FIG. 2




FIG. 3

ROLLER AND AIR JET ASSEMBLY




FIG. 4A

ROLLER AND AIR JET ASSEMBLY





FIG. 4A



AIR JET FUNCTION

AIR JET ASSEMBLY SIDE VIEW




FIG. 5

160
↙

INSERT HOPPER SIDE VIEW




FIG. 6

INSERT HOPPER TOP VIEW




FIG. 7

INSERT HOPPER BOTTOM VIEW




FIG. 8






FIG. 9

FIG. 10A

HOPPER ADJUSTMENT ASSEMBLY
SIDE VIEW



HOPPER ADJUSTMENT ASSEMBLY
TOP VIEW

FIG. 10B




FIG. 11 TOWER WITH HOPPER ADJUSTMENT ASSEMBLY

SENSORS SIDE VIEW





FIG. 12






FIG. 14

1500



MULTIPLE INSERT DELIVERY SYSTEM




FIG. 15




FIG. 16




Fig. 17

Fig. 18





Fig. 19






Fig. 20

Fig. 21





Fig. 22






Fig. 23




Fig. 24